



Description:	Lounge Chair w/ left facing power source / USB Port
Model Number:	HC09489-05PL
Model Name:	Liev
Width:	33"
Height:	40"
Depth:	36"
Seat Width:	22.5"
Seat Height:	20.5"
Seat Depth:	20.5"
Arm Height:	26.5"
Seat Cushion Style:	Loose reversible, Nylon Zipper closure in casings.
Seat Cushion Content:	Comfort Firm ; 2.3 High foam core wrapped in two layers of plush foam encased in a moisture resistant barrier. All cushions and padding materials meet UFAC.
Seat Support:	8 gauge 60% post consumer recycled sinuous steel springs spaced 5" apart, inter spring connected with two tie wires. Spring system to be secured with additional hardwood stabilizer front rail and covered with heavy duty batting and seat denim.
Back Cushion Style:	Tight
Back Cushion Content:	10-12 Gauge 60% post consumer recycled sinuous steel springs secured with insulated self lubricating clips and innerspring connected with steel tie wires. Spring support system covered in heavy duty batting, high resilient foam and 1 oz fiber.
Frame:	Frame stocks are harvested from certified sustainable sources. All stress joints to be connected utilizing one of the following, Double Doweled, screwed and glued - corner block, glued and Heavy Duty Frame Staples. Glue is polyvinyl acetate.
Finish:	Durable Catalyzed finish, HAPS free (Hazardous Air Pollutants), Microban antimicrobial treatment, UV inhibitor, and resistant to cleaning chemicals.
Warranty:	Frame and Springs - 10 years Cushions - 3 years Power Source - 1 year
Additional Notes:	Legs are removable. Wrinkling is an inherit characteristic on the top of the arm of this group when using certain fabrics. Power source contains two outlets and two USB ports. Electrical outlets and USB ports are designed for occasional use only. Keeping a device or electrically powered unit plugged in continuously may be viewed as "permanent wiring", and create a fire code violation. It is the purchaser's/ customer's responsibility to comply with all federal, state and local regulatory fire codes. Kellex does not assume responsibility for improper use of the outlets and USB ports.

www.kellex.com